

## Risk Management Committee / Review of Injuries

Dates Reviewed: November 11 to December 9, 2020

<b>Injury Type</b>	Laceration to forehead
<b>Description of Accident</b>	Employee was dropping the drive shaft. A jack stand was placed under the shaft. When removing the last bolt from the carrier holding the drive shaft rotated. Employee left his impact wrench on the bolt while trying to stop the drive shaft from rolling. The impact wrench fell on the employee's forehead.
<b>Corrective Measures</b>	Add a jack stand or strap/chains to cradle the u joints. Ask for assistance if necessary.
<b>Employee Vehicle Accidents</b>	
<b>Description of Accident</b>	Employee was on a service call. While backing the service vehicle out of traffic, struck the corner of the awning.
<b>Corrective Measures</b>	Check your surroundings before backing. GOAL: Get Out and Look. Finally, could have asked someone to spot for them while backing.

Please make sure all injuries are reported to [AccidentsAndInjuries@starlease.com](mailto:AccidentsAndInjuries@starlease.com) in a timely manner. Go over with all shifts where the Injury reports are kept so they are accessible. Injury reports should be completed and turned in even if no medical treatment is given.

Our goal is for employees to punch out in the same condition that they came into work.

**Branch:** \_\_\_\_\_ **Date:** \_\_\_\_\_

Review of Injuries from November 11 to December 9, 2020

**DUE: January 16, 2021**

# Participants

Please print name:
