

Risk Management Committee / Review of Injuries

Dates Reviewed: January 1 to February 6, 2020

Injury Type	Contusion to right index finger
Description of Accident	Employee was using sledge hammer to remove a seized inner rear tire. The hammer missed the tire, and pinched the finger between hammer handle and rear hub.
Corrective Measures	Make sure jack stands are being used, slide under the truck and hit from the back side. If that doesn't work, try standing and hit the tire. Be careful while doing so
Injury Type	Injury to eye, cheek and left knee
Description of Accident	Employee was greasing a truck. While trying to move work cart of the way, tripped and fell over the grease hose
Corrective Measures	Make sure all obstacles are out of the way before moving the cart. Be aware of your surroundings and when where you are walking.
Injury Type	Contusion to right leg
Description of Accident	Employee was walking past a truck. Employee struck his right leg on the driver's side lower step.
Corrective Measures	Be aware of your surroundings while walking.
Injury Type	Eye injury: foreign object
Description of Accident	While rolling under a snow-covered truck to change oil filter, a foreign object fell into the eye. Employee was wearing safety glasses
Corrective Measures	Wear safety goggles while working under trucks.
Injury Type	Sprain to right foot
Description of Accident	While doing morning yard check in the dark, slipped on ice that was in between trucks.
Corrective Measures	Employees should use a flashlight when walking dark areas in the parking lot to identify icy areas. Also, employee could use boot cleats and a hand salter if needed. Finally, an employee should walk like a penguin in icy conditions.
Injury Type	Fracture to wrist, contusion to shin and knee
Description of Accident	Employee was walking on platform ladder. Employee took a step back too far and slipped and fell off from platform
Corrective Measures	Pay attention while working on the platform before taking a step back. Employees should make sure they aware of their surroundings. Finally, employees should not be distracted while walking or working. No use of wired or wireless headphones/earbuds is allowed.

Our goal is for employees to punch out in the same condition that they came into work.

Injury Type**Description of Accident**

Fracture to left pointer finger

Two engines were sitting on pallets. Employee was transferring the air compressor from old to new engine. Employee was using both hands – one on top inside edge and other on the back. When employee moved right hand off the back of the compressor to start a bolt, the compressor rolled in the coupler and smashed left pointer finger. The finger was smashed between the compressor and engine block.

Corrective Measures

Ask for assistance to complete this task.

Please make sure all injuries are reported to AccidentsAndInjuries@starlease.com in a timely manner. Go over with all shifts where the Injury reports are kept so they are accessible. Injury reports should be completed and turned in even if no medical treatment is given.

